





Technical Update

Technical Update Brew Valve Exhausts

All Machines built before 2018 or any machine with non metal brew valve exhaust need to be updated. To check if you need updated brew valve exhausts please remove the top cover on the group tower with 3mm allen key (same tool used removing group screens)



Please review the photos shown to make sure you have the proper exhaust fitting to avoid leaks and component failure.



The update part number is MV-NEW-BREW-EXHAUST Please contact parts@mavamespresso.com or support@mavamespresso.com